



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



New Mexico State University  
Fire Safety Reporting [18] HEOA  
Reporting Date: January 1, 2015 to December 31, 2015

---

*NOTE: All fire drills reported below are supervised, meet International Fire Code Chapter 4 Emergency Planning and Preparedness, and have mandatory evacuation for all individuals. During the fire drills there is an inspection of: audio sound, synchronization of light strobes, exit doors, and other factors of the system in place.*

---

#### **I. On-campus student housing facilities, description of the facilities and description of fire safety system.**

##### **Residence Halls**

###### **Garcia Hall (1715 International Mall)**

Garcia Hall is a three story fire resistive building with four patios. Dorm rooms encircle the patios.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/16/2015

One fire reported. Information is in section **II Fire Statistics**.

###### **Piñon Hall**

Piñon Hall is a three story wood frame structure. The building is two separate sections connected by a common area. Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/16/2015



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



#### Rhodes-Garrett-Hamiel (RGH)

RGH is a three story fire resistive building with traditional dorm rooms off the main hallway.

Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Hallways and corridors are protected by with an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 01/28/2015
- Fire Drill: 1 on 09/08/2015

### Campus Apartments

#### Cervantes Village

Cervantes Village are multiple single story wood frame buildings, they contain one, two, and four bedroom apartments.

Fire Protection: The rooms contain individual smoke detectors and CO alarm detectors.

Six fires reported. Information is in section [II Fire Statistics](#).

Five fires considered suspicious. Information is in section [II Arson Fires](#).

#### Chamisa Village I & II

Chamisa Village is a complex made-up of three story wood frame buildings. Apartments come in two and four bedroom layouts.

Fire Protection: Apartments contain individual smoke detectors. Pull stations and smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and main areas are protected by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

#### Chamisa Village I

- Fire Drill: 1 on 01/27/2015
- Fire Drill: 1 on 09/10/2015



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



Chamisa Village II

- Fire Drill: 1 on 01/27/2015
- Fire Drill: 1 on 09/10/2015

Two fires reported. Information is in section [II Fire Statistics](#).

#### **Vista Del Monte (3540 Research Dr.)**

Vista Del Monte is a complex made up of two story wood frame buildings. Apartments are in two-bedroom configuration.

Fire Protection: Apartments contain individual smoke detectors and CO detectors.

Two fires reported. Information is in section [II Fire Statistics](#).

### **Family Housing**

#### **Tom Fort and Sutherland Villages (426 McArthur Dr.)**

Tom Fort and Sutherland are single-family, single story fire resistive homes.

Fire Protection: The homes contain individual smoke detectors and CO detectors.

One fire reported. Information is in section [II Fire Statistics](#).

#### **Cole Village (2215 John Loveland Ave.)**

Cole Village are two story fire resistive town houses, they are two bedrooms configuration.

Fire Protection: Each home contains individual smoke detectors and CO detectors.

One fire reported. Information is in section [II Fire Statistics](#).

### **Greek Housing**

#### **Greek & ROTC West (Buildings 100-400)**

Greek Complex West is made up of four sections. They are single story fire resistive dormitory buildings.



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



Fire Protection: Dorm rooms contain individual smoke detectors. Pull stations are monitored by a fire alarm system. It reports directly to our dispatch center.

- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/10/2015

#### **Greek Complex East (Buildings 500-800)**

Greek Complex East is made up of four, two story wood frame building, each section contains four bedrooms.

Fire Protection: Pull stations and smoke detectors in the hallways, they are monitored by a fire alarm system. The system reports directly to our dispatch center. Each individual bedroom has a smoke detector in place; they are not on the fire alarm reporting system.

- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/10/2015

One fire reported. Information is in section **II Fire Statistics**.

#### **Chi Omega**

Chi Omega is a residential sorority, two story wood frame home.

Fire Protection: Bedrooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/08/2015

#### **Delta Zeta**

Delta Zeta is a residential sorority, single story wood frame home.

Dorm rooms contain individual smoke detectors. Smoke alarms in the common areas are monitored by a fire alarm system. It reports directly to our dispatched center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/08/2015

#### Zeta Tau Alpha

Zeta Tau Alpha is a residential sorority, two story wood frame home.

Fire Protection: Smoke detectors throughout the building and pull stations in the hallways are monitored by a fire alarm system. It reports directly to our dispatch center. Rooms and common areas are covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

- Fire Drill: 1 on 01/29/2015
- Fire Drill: 1 on 09/08/2015

### Academic Buildings

#### Business Complex Center (1320 University Avenue)

Business Complex Center is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: Business Complex Center is equipped with a full addressable fire alarm system.

Fire Drill on 09/08/2015

#### International Public Policy Building (3014 McFie Circle)

International Public Policy Building (IPP) is a multi-story Fire Resistive Non-Combustible building that houses offices, lecture rooms, and classrooms.

Fire Protection: IPP is equipped with a full addressable fire alarm system and a sprinkler fire suppression system.

Fire Drill on 09/08/2015

One fire reported at Burrell College. Information is in section [II Fire Statistics](#).



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



#### Non-Academic Buildings

##### Dove Hall (1305 North Horseshoe)

Dove Hall is a Fire Resistive Non-Combustible building that houses offices.

Fire Protection: Dove Hall is equipped with a full addressable fire alarm system and is covered by an automatic wet pipe sprinkler system. The fire sprinkler system is inspected quarterly and maintained to NFPA 25.

Fire Drill on 09/09/2015

##### Garcia Annex (3024 Andrew Wall Place)

Garcia Annex is a Fire Resistive Non-Combustible building that houses offices, lecture rooms, and individual clinical rooms.

Fire Protection: Garcia Annex is equipped with a full addressable fire alarm system.

Fire Drill on 09/16/2015

##### Kent Hall (1280 University Avenue)

Kent Hall is a Fire Resistive Non-Combustible building that houses offices and a two-winged museum.

Fire Protection: Kent Hall is equipped with a full addressable fire alarm system.

Fire Drill on 09/08/2015

Four fires reported in non-academic buildings. Fires were at Stucky Hall, Aggie Memorial Stadium, Corbett Center, and Barnes and Noble Bookstore. Information is in section [II Fire Statistics](#).

#### Fatality or Casualty Fires

None



# NMSU Fire Department

## 2016 Annual Fire Safety Report

### Clery Act Requirement



## II. Fire Statistics

### 2015 Digital Fire log

DATE	ADDRESS	INCIDENT
02/04/2015	1506 Standley DR (Tom Fort Village)	NFIRS 113 - Cooking fire, confined to container
03/21/2015	Corner of Sweet Avenue and Greg Street (Preciado Park)	NFIRS 150 - Outside rubbish fire, other
04/13/2015	3545 Williams ST. # W27B (Vista Del Monte Apartments)	NFIRS 111 - Building fire
04/30/2015	3170 Espina ST (Stucky Hall)	NFIRS 118 - Trash or rubbish fire, contained
05/08/2015	2625 Locust ST (Garcia Hall)	NFIRS 118 - Trash or rubbish fire, contained
07/29/2015	1390 Standley DR # B-2 (Cervantes Village)	NFIRS 162 - Outside equipment fire
08/18/2015	3120 Locust ST (Chamisa Village)	NFIRS 151 - Outside rubbish, trash or waste fire
08/22/2015	Corner of Wells St. & Locust Ave. (Greek Housing)	NFIRS 131 - Passenger vehicle fire
09/02/2015	1455 Standley DR # R3 (Vista Del Monte Apartments)	NFIRS 113 - Cooking fire, confined to container
09/02/2015	1390 Standley DR # B-6 (Cervantes Village)	NFIRS 111 - Building fire
09/14/2015	4203 Sam Steel Way (Cervantes Village)	NFIRS 118 - Trash or rubbish fire, contained
09/16/2015	4201 Sam Steel Way (Cervantes Village)	NFIRS 151 - Outside rubbish, trash or waste fire
09/18/2015	4201 Sam Steel Way (Cervantes Village)	NFIRS 151 - Outside rubbish, trash or waste fire
09/19/2015	1810 Stewart ST (Aggie Memorial Stadium)	NFIRS 113 - Cooking fire, confined to container
09/21/2015	1651 Wooten DR (Cole Village)	NFIRS 111 - Building fire
09/26/2015	4401 SAM STEEL WAY # J (Cervantes Village)	NFIRS 118 - Trash or rubbish fire, contained
09/27/2015	3020 Andrew Wall PL (Chamisa Village)	NFIRS 131 - Passenger vehicle fire
10/12/2015	3600 Arrowhead Park (Burrell College)	NFIRS 111 - Building fire
10/25/2015	1600 International Mall Room 148 (Corbett Center)	NFIRS 100 - Fire, other
12/01/2015	4201 Sam Steele Way (Cervantes Village)	NFIRS 118 - Trash or rubbish fire, contained
12/08/2015	1400 E University Ave (Barnes & Noble)	NFIRS 154 - Dumpster or other outside trash receptacle fire



# NMSU Fire Department 2016 Annual Fire Safety Report Clery Act Requirement



## Arson Fires

### Cervantes Village (Sam Steele Way)

New Mexico State University Fire and Police Department responded to damage done to and around trash dumpsters in Cervantes Village. An underage person of interest was identified.

Five arson fires reported and investigated. Information is in section II [Fire Statistics](#).

### III. New Mexico State University Fire Prevention Guidelines and Practices

Found online at: <https://fire.nmsu.edu/fire-prevention-guidelines/>

### IV. 2015 Annual Security Report, New Mexico State University Police Department

Found online at: <https://www.nmsupolice.com/annual-reports/>

### V. 2015 Annual Reports, New Mexico State University Fire Department

Found online at: <https://fire.nmsu.edu/annual-reports/>

New Mexico State University Fire Department offers free Portable Fire Extinguisher Training. To sign up for a class, go to Training Central: <https://trainingcentral.nmsu.edu/>.